


Table of tolerances for dial indicators according to DIN 878.

(Tolerance according to DIN 7168/1).

Max permitted measuring deviation for all measuring ranges.

(Reference temperature +20°C.)



Measuring range	mm	0.4	0.8	3	5	10
Max deviation incl. backlash	μm	9	9	12	14	17